

Attachment C

East Plum Creek Stream and South Well Field Improvements

Site Photos



Looking south – bank erosion along well field fence.



Looking northeast – bank erosion along well field fence.



Looking west – Well 13AL just inside fence near eroded bank.



Looking northwest – Well 12R cleanout in creek.



Looking west – Well 204 drain line at east bank.