ATTACHMENT A	4
TOWN OF CASTLE ROCK COLORADO	
Before completing this application, a pre-application meeting must be scheduled, please contact Julie Kirkpatrick at 720-733-3516 or jkirkpatrick@crgov.com	
Pre-Application meeting to discuss the project and the application process	
Applicant and Owner Information:	
Applicant Name <u>Bruce & Kimberly</u> Phone <u>303 905 4115</u> E-mail Kimberly decker @ Decker Check one: Q Owner I Tenant G Mail. COV	m
Property Owner Name Same Phone E-mail	
Home Address 203 N. Cantril St., Castle Rock, CO SO104 Business Name and Type	
Business Address	
(Street address, name of building, if applicable) Building Name_Hammark (Forse_Date of construction [9]) The structure of the	
Sale of construction I ype construction J C F IE	
Register Status:	
All buildings that are applying for local grant assistance must be registered as local landmark. Yes, my property is registered as a local landmark	
Project Description:	
Type of Work (Please check what applies)	
□ Walls/Fencing/Landscaping □ Façade □ Repair or replacement of windows and doors ☑ Painting □ Awning □ Signs □ Reconstruction □ Reroofing □ Other (Please Explain) replacement of windows and doors ☑ Reconstruction ∨ eplace 3 doors (exter(ur))	
Describe the building's existing and proposed uses	
Describe any damage or required repairs that are forcing improvements <u>Paint</u> is <u>deteriorating</u> ; <u>Siding</u> <u>Very brittle</u> ; raw wood <u>exposed</u> ; <u>gutters</u> in <u>very</u> <u>bad</u> <u>shape</u> ; <u>leaking</u> , <u>3</u> <u>doors</u> <u>need</u> <u>replacement</u> - <u>2</u> <u>are</u> <u>not</u> <u>original</u> ; <u>but</u> <u>all</u> <u>3</u> <u>have</u> <u>cracks</u> <u>so</u> <u>you</u> <u>can see</u> <u>light</u> <u>through</u> <u>door</u>	/

CASTLE ROCK	E ROCK LOCAL GRANT ASSISTANCE APPLICATION Development Services 100 N Wilcox Castle Rock, CO 80104
Describe desired design improvements Sec atta	ched
Any additional Information	
Project Attachments	
 The following items must accompany this application, (if Project Budget Photographs of the building (all sides) or site Preliminary sketch or photographic examples of proposed chan Proposed Timetable Independent estimates for materials and other costs (at least 2, planet) and the contractor's or consultant's estimates (at least 2; planet) 	ges
PLEASE NOTE THAT ALL REIMBURSED WORK MUST BE PER	FORMED BY A LICENSED CONTRACTOR.
9,959,55 Grant Request: \$ 19,959,55 Signature of Owner Khiztle	Cash Match \$ 9959.55
Development Services, Staff use only	
Date of Initial Contact	
taff Representative:	
roject Funding	
pplicant will pay \$	τ-) τ-
Pre-Application Meeting 🗅 Post-Application Meeting 🗅	Historic Preservation Board: Approved 🖵 Denied 🖵

Project Description and Desired Design Improvements


This project involves a number of separate tasks all designed to improve the exterior condition of the Hammar House, and in some cases, prevent ongoing damage to the structure.

1) Exterior paint for siding and trim (fascia and soffits): In 2017 and 2018, we repaired, restored and painted the siding for the wood section of the house. We completed that work ourselves, and consequently, we were only able to safely work up to the top of the first floor level. We need help with repairs and restoration of the siding at the 2nd story level, as well as all fascia and soffit wood on the wood section (some of which is at a height of ~30 feet).

2) Replacement of gutters: the gutters are in terrible condition and need to be replaced. Further, we need to improve downspouts to keep water away from the window wells and foundation.

3) Replacement of 3 exterior doors: We have a total of 5 exterior doors, three of which were original "tombstone" doors with 2 arched windows. We restored on of those doors - which was a very timeconsuming and expensive process for us - and that was a mistake. The doors are only one-inch thick, subject to significant warping, and we simply cannot buy hardware that works properly due to the limited thickness. We found a company that will make a solid wood reproduction "Tombstone" door and in 2018 we replaced one of the original doors that was broken beyond repair. In addition, we found period-appropriate reproduction door hardware. for the current project, we need to replace 3 doors (only one of which is original but it is only 1" thick and is cracked beyond repair. We also need new door hardware for these 3 exterior doors. Our plan is to hand these doors in the original wood frames, which we will be restoring ourselves prior to installation of the doors.

Pictures:




North side

West side:



South side:



East side:



Proposed Timetable:

Doors have already been ordered. Work expected to be complete by the end of Summer 2019.

Proposed budget:

	Qty		Aı	nount	To	otal
Exterior painting and siding repair, including						
provisions for working with lead paint		1	\$:	11,074.19	\$	11,074.19
Gutter replacement		1	\$	2,447.06	\$	2,447.06
3 exterior door slabs		3	\$	1,094.46	\$	3,283.38
7% sales tax		1	\$	76.61	\$	76.61
3 sets door hardware & hinges		3	\$	474.87	\$	1,424.61
7% sales tax		1	\$	33.24	\$	33.24
Door hanging and hardware installation		1	\$	1,580.00	\$	1,580.00

Grand Total

\$ 19,919.09

1115280EXTERIORS

Quote

Customer ID: PR7420 Date: 1/8/2019

5280 Exteriors

Guy Grignon 8200 East Pacific Place #301 Denver, CO 80231 Direct: (303) 815-8213 Office Phone: (720) 707-6963 Fax: (303) 362-5524 Email: office@5280exteriors.com

TO Kim Decker 203 Cantril Street Castle Rock, CO 80104 kimberly.decker@gmail.com (303) 905-4115

Quote valid through: 1/31/2019

Description: This proposal is for painting the property at 203 Cantril Street in Castle Rock. We will be painting the surfaces with two coats of Benjamin Moore Regal Select Exterior paint in a soft gloss finish. We will be prepping and painting the soffits and fascia as well as the upper gable section of siding on the north side of the house. We will also be repairing the fascia where the gutters are to be installed to provide a sound surface to mount the gutters. We will be installing an additional gutter and downspout along the eave on the south side of the roof. In addition we will be installing 6" aluminum gutters and downspouts. I have also provided an alternate price for substituting 6" half round gutters with downspouts. Since this property was built in 1881, Federal Law requires that we test for the presence of lead in the paint. If the lead test is found to be positive at levels beyond acceptable standards, then lead containment will be required in any areas where the painted surfaces need to be scraped or disturbed. This proposal does not include painting any windows, doors or window door trim. Does not include underground work on northwest corner for gutter drain.

I propose to furnish all materials, sales tax and perform all labor neccessary to complete the following work:

Product	Qnty	Unit of Measure	Description	Unit Price	Total
Prep-Work for Painting	24.0	each	Power Wash, Scrape, Feather Sand, Spot Prime, SherMax Caulking, Mask/Tape. "Feather sanding" is defined as lightly sanding areas that have been scraped where there is a transition from raw wood to old paint. The purpose is the lessen the appearance of the transition. Engineered woods cannot be sanded. Highly damaged wood (including engineered wood) that retains moisture is at risk of delamination, which is not caused or cured with paint preparation. Prep work excludes caulking any nail holes unless noted otherwise in a separate line item.	\$ 35.51	\$ 852.24
			If paint is found to contain lead above acceptable limits, power washing and sanding will not be allowed. Only scraping, spot priming and caulking.		
Spot Prime Option: Caulk/Primer Mix	1.0	each	For older homes that have previous coats of oil based paints that cannot be sanded or very rough surfaces, 5280 will apply a primer/caulking mix (paste texture) that will better cover the imperfections when spot priming. Note: since the mix is thick, brush and roll marks will be more apparent.	\$ 108.00	\$ 108.00
Sundries Paint	1.0	Tot.	Necessary materials for the proper completion of your paint project.	\$ 108.00	\$ 108.00
Setup / Cleanup Paint	1.0	Tot.	Time and materials necessary for proper preparation and clean up of your paint project.	\$ 120.96	\$ 120.96
Flat Surface Siding - Brush application only.	172.0	sqft	Finish painting the lap siding above where it has been started on the north side of the house. 2 coats Benjamin Moore Regal Select Soft Gloss finish.		\$ 964.92
Soffit Paint - Hand brush only RES	689.0	sqft	Apply two coats of Benjamin Moore Regal Select Exterior paint. Soft Gloss finish.		\$ 3,706.82
Fascia - Hand Brushed	244.0	LinFt	Apply two coats of Benjamin Moore Regal Select Exterior paint in a soft gloss finish.		\$ 1,080.92
Fascia Replace.	98.0	LinFt	Remove crown molding under gutters and install wood fascia board to allow for better and more secure placement of gutters. Includes sub-fascia. Fascia is to be replaced on level fascia only, not rake fascia. If deeper woodwork damage is found to be necessary upon removal of existing wood, there may be an additional charge to repair.		\$ 1,956.08
Remove Existing Gutters GT	210.0	LinFt	Remove and dispose of existing gutters and downspouts.		\$ 350.70
Gutters Larger 6" GT	98.0	LinFt	Seamless Aluminum. Contemporary design. Large selection of prefinished colors.		\$ 974.12
Gutters Larger 3" x 4" Downspouts GT	112.0	LinFt	Seamless Aluminum. Includes elbow at bottom of the downspout. Downspout extensions are quoted separately.	\$ 10.02	\$ 1,122.24
Notes			"Optional Pricing" for 6" half round gutters and round downspouts for a more historical look. Available in brown, white or grey prefinished color. If a different color is desired gutters will need to be painted for an additional charge. The cost for this line item is \$5814.90 vs \$2096.36 for standard contemporary 6" gutters and downspouts as in line items above.	\$	\$ 0.00
Paint Roof protrusions	6.0	Ea	Paint 4 roof protrusions and two chimney flashings.		\$ 450.00
Paint Lead Paint Containment		each	Per story. EPA required lead paint containment if the lead test is found to be positive above Federal limits. Cost is \$1396 per story.		\$ 0.00
Lead Paint Test	1.0	Ea.	EPA approved lead paint test by an independent 3rd party. Required for homes built prior to 1978. Questions? https://www.epa.gov/lead/lead-renovation-repair-and-painting-program-rules		\$ 150.00
Permit Fee	1:0	Ea	If a permit is necessary we will obtain it and you will be charged the applicable fee at the end of your project.		\$ 0.00
Portable Toilet Fee	1.0	Ea.	Required for multiple day jobs	\$ 180.25	\$ 180.25
			······································	Subtotal	\$ 12,125.25

Total \$ 12,125.25

\$ 0.00

Sales Tax

All work is to be completed in a substantial and workman-like manner for the sum above. Payment can be made by check or money order to 5280 Exteriors.

For projects \$40,000 and under, payment is to be made as follows:



Ron Goings (720-879-2156) rgoings@sunmountaindoor.com

140 Commerce Drive Berthoud, CO 80513 Ph: 970-532-2105 Fax: 970-532-2208

Quotation

MADE IN THE USA

Quote ID: 112909 **Expiration Date:** 01/29/2019

DECKER, KIMBERLY 112909

Quotation For:

DECKER, KIMBERLY

203 CANTRIL STREET CASTLE ROCK, CO 80104 Ph: 303-905-4115 kimberly.decker@gmail.com

8 Weeks

Project:

203 CANTRIL STREET CASTLE ROCK, CO 80104

Salesrep


Lead Time


Comments

_	LINE	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
	1	1	2/10 x 6/8-5/8x 1-3/4 O4 2-Panel/2-Lite (2W1H) Top Rail True Arch Select Poplar, L1= 31, Clear IG, Slab Only, No Bore CUSTOM LAYOUT PER DRAWING 112909A_1_1 Primed Satin. SOUTH SIDE ENTRY	1,258.00 (-13%)	1,094.46
	2	1	2/10 x 6/9-1/4x 1-3/4 O4 2-Panel/2-Lite (2W1H) Top Rail True Arch Select Poplar, L1= 31, Clear IG, Slab Only, No Bore CUSTOM GLASS LAYOUT PER DRAWING 112909A_2_1 Primed Satin. WEST SIDE ENTRY	1,258.00 (-13%)	1,094.46
	3	1	 2/8 x 6/7-1/2 x 1-3/4 O4 2-Panel/2-Lite (2W1H) Top Rail True Arch Select Poplar, L1= 31, Clear IG, Slab Only, No Bore - CUSTOM GLASS LAYOUT PER DRAWING 112909A_3_2 Primed Satin. ANGEL DOOR 	1,258.00 (-13%)	1,094.46
	4	1	2/2 x 6/7 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Right Hand, 4-3/4" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. 1ST FLOOR HALL CLOSET Unit size: 27,5 x 81,25	635.00	635.00
	5	1	2/1 x 6/7 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Right Hand, 4-5/8" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. UNDER STAIRS	635.00	635.00
L			Unit size: 26.5 x 81.25		


LINE	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
6	1	2/8 x 6/7 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Left Hand, 4-7/8" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. MASTER CLOSET	635.00	635.00
		Unit size: 33.5 x 81.25		
7	1	2/8 x 6/7 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Left Hand, 4-7/8" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. 2ND FLOOR BATH	635.00	635.00
		Unit size: 33.5 x 81.25		
8	1	2/8 x 6/8 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Left 635.00 Hand, 4-3/4" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. LAUNDRY		635.00
		Unit size: 33.5 x 82.25		
9	1	1/11-1/2x 6/7 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Left Hand, 4-7/8" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. TOILET ROOM	635.00	635.00
		Unit size: 25 x 81.25		
10	1	2/2 x 6/8 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Right Hand, 4-5/8" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. LINEN CLOSET	635.00	635.00
		Unit size: 27.5 x 82.25		
11	1	1/11 x 6/8 x 1-3/8 Teton Raised 4-Panel Square Select Poplar, Left Hand, 4-3/4" Select Poplar Flat Jamb, No Bore, Antique Nickel Hinges, Primed Satin. LAUNDRY CLOSET Unit size: 24.5 x 82.25	635.00	635.00
12	1	Drop Fee (x\$105.00)		
		ΤΔΥΔΙ	BLE SUBTOTAL	\$2 262 20
			SALES TAX	\$8,363.38 \$ 577.12
			DELIVERY	\$ 577.12
		OTHER SERV		\$ 0.00
			TOTAL	\$ 9,045.50

...






"*" = NON-STANDARD COMPONENT



HOUSE OF ANTIQUE HARDWARE

www.HouseofAntiqueHardware.com (888) 223-2545 9:00 am - 8:30 pm M-F, Eastern


GRANDEUR "WINDSOR" ENTRY DOOR SET WITH WINDSOR KNOBS



HOUSE OF ANTIQUE HARDWARE

www.HouseofAntiqueHardware.com (888) 223-2545 9:00 am - 8:30 pm M-F, Eastern

3 1/2" BALL-TIP WINDSOR PATTERN HINGE IN SOLID BRASS



3 1/2" Ball-Tip Windsor Pattern 3 1/2" Solid Brass Eastlake Steeple From \$12.99 From \$21.79

kimberly.decker@gmail.com

From:	rosswindows2000 <rosswindows2000@yahoo.com></rosswindows2000@yahoo.com>			
Sent:	Sunday, February 3, 2019 12:38 PM			
То:	kimberly.decker@gmail.com			
Subject:	Re: door hanging estimate			

Rough draft estimate , written final contract. When ready to move forward. Installation 3 exterior doors. Historical Restoration. Prep area for installation Remove existing 3 exterior doors, hardware etc. Remove existing door stop, around 3 door jambs. Install new door stops, 3 existing door jambs, to accommodate customer new doors. Mortise hinges 3 doors, cut, shave, sand edges to accommodate 3 preexisting door jambs. Install new doors. Prime raw wood edges where needed. Bore 3 doors, install customer hardware, knob sets, etc. Clean up and haul off door debris. 3 to 4 day completion Material and labor total \$ 1,580.00 Thank you for your business, Wayne Ross Ross windows and doors 720-270-9512

Sent from my Verizon, Samsung Galaxy smartphone

------ Original message ------From: kimberly.decker@gmail.com Date: 2/2/19 6:33 PM (GMT-05:00) To: rosswindows2000@yahoo.com Subject: door hanging estimate

Please reply to this email with the estimate.

kim