



Castle Oaks Drive Bridge Repair



Current Condition




Current Condition



This photo shows the underside of the steel bridge. There are visible signs of deterioration to the corrugated metal, including corrosion, water intrusion and section loss and scaling. Overall this pictures shows advanced corrosion that requires repairs or replacement.

Detour – October 11 through 28



Communication Plan

- Project board at District 2 Councilmember open house with project manager in attendance, September (done)
- Know before you go social media posts on Facebook and Nextdoor – concrete repairs and paving ahead of bridge work, with mention of bridge work, September (ongoing)
- Project page on CRgov.com, September
- News release, October
- Your Town Talk article, October issue
- Know before you go social media posts – Facebook and Nextdoor ahead of work, October
- Post VMS boards