

Attachment B: Photos of Existing Conditions

Soffits/Gutters/Fascia



Attachment B: Photos of Existing Conditions (Continued)

Windows




Attachment B: Photos of Existing Conditions (Continued)

Masonry



Attachment B: Photos of Existing Conditions (Continued)

Basement Water Intrusion



Fire Escape

